

Technical Data Sheet

Pressure / Temperature / Humidity / Air Velocity / Airflow / Sound level




Pt100 temperature converter CO-LC

DESCRIPTION

The **CO-LC** converter is a converter of Pt100 temperature in a **4-20 mA** electric signal adjustable for Pt100 temperature sensors. It enables to convert the temperature variations measured by a standard Pt100 sensor (**100** Ω **at 0** °C) for a measuring range in linear signal of a 2-wire current in the **4-20 mA** domain.


The converter is protected against the polarity inversion and has been designed to be placed in a **DIN B** probe head.

DIMENSIONS (in mm)



OUTPUT CURRENT ACCORDING TO TEMPERATURE

(in a 0 to +100 °C domain)



CONVERTER FEATURES

(at 20 °C and for a 24 Vdc supply voltage)


| • Input | |
|---|---|
| Sensor | Pt100 (100 Ω at 0 °C) |
| Element mounting | 2 or 3 wires |
| Linearization | EN60751, IEC 751 |
| Current in the sensor | <1 mA |
| Measuring range | From -50 to +100 °C |
| Range by default | From 0 to +100 °C |
| Other available ranges | From 0 to 50 °C From -20 to 80 °C From -50 to 50 °C |
| Minimal measuring range | 50 °C |
| Connection wires influence | Negligible with coupled wires |
| Accuracies | ±0.2 °C ±0.2% of reading |
| Sensitivity to the ambient temperature variations | 0.01 °C/°C |
| Sensitivity to the supply voltage variations | 0.005% FS / Vdc (FS : full scale) |
| Storage temperature | From -40 to +80 °C |
| Operating temperature | From 0 to +50 °C |

Output

| Output | 4-20 mA |
|----------------|---|
| Resolution | 2 μΑ |
| Supply voltage | 7-30 VDC (protection against polarity inverions) |
| Output burden | $R_{Lmax} = \frac{Vdc - 7}{0,022}$ |
| | =>R $_{\text{Lmax}}$ = 825 Ω at Vdc = 24 Vdc |

CONNECTION

The **figure 2** shows the connection diagram of the converter in the current loop. In order to obtain a better accuracy, use 3 wires with the same diameter to make the connection to the Pt100 probe to ensures the same impedance in each connection. A device can be introduced in the current loop like a display unit, a controller or a datalogger.



ADJUSMENT

It is possible to set a different measuring range by using the following accessories:

- Continuous 24 Vdc power supply source
- $^{(1)}$ Very precise ammeter with aminimal range from 0 to 20 mA.
- 2 Pt100 calibrator

(3)

Procedure:

• Connect the converter to configure to the source of the power supply, to the ammeter and to the Pt100 (see figure 2).

a - Configuration of T1 point

Generate the corresponding resistance to the T1 temperature (For example: for 0 °C simulate 100 Ω). With the help of the potentiometer \emptyset (offset), adjust the current output of the transmitter to obtain 4 mA.

b - Configuration of T2 point

Generate the corresponding resistance to the T2 temperature (For example: for 100 °C simulate 138,51 Ω or 100 °C on the Pt100 calibrator). With the help of the G potentiometer (gain), adjust the current output of the transmitter to obtain 20 mA.

c – Check the adjustment

Redo the a and b points until you obtain the 4 mA and 20 mA signals for the T1 and T2 setpoints.



fao

9001

A modification of the gain or the offset can influence the adjustment.

PT100 VALUES IN OHMS ACCORDING TO THE MEASURED TEMPERATURE (FOR REFERENCE ONLY)

| Temp °C | PT100 value |
|---------|-------------|
| -200 | 18,52 |
| -150 | 39,72 |
| -100 | 60,26 |
| -50 | 80,31 |
| 0 | 100,00 |
| 50 | 119,40 |
| 100 | 138,51 |
| 150 | 175,86 |



EXPORT DEPARTMENT Tel : + 33. 1. 60. 06. 69. 25 - Fax : + 33. 1. 60. 06. 69. 29 e-mail : export@kimo.fr Distributed by :

